



Concrete Overlay Webinar Series Performance History of Concrete Overlays





- **Case Histories**
- 2014 CP Tech Center publication

– free download!

November 2014 PERFORMANCE HISTORY OF CONCRETE **OVERLAYS IN THE UNITED STATES**



www.cptechcenter.org





Case Histories

 Highlights twelve concrete overlay projects across the US





Concrete Overlay Case Histories

				Existing Paver	ment Type and C	verlay Type	Functional Classification			
Case History #	State	Route	Year Constructed	Asphalt	Composite	Concrete	Interstate or Freeway or Expressway	Principal or Minor Arterial	Major or Minor Collector	Local
1	ОК	US-69	2001	Bonded				$\overline{\checkmark}$		
2	MT	US-16	2001	Bonded					$\overline{\checkmark}$	
3	IL	Plank Rd	1974	Unbonded						$\overline{\checkmark}$
4	СО	US-287	1998	Unbonded				$\overline{\checkmark}$		
5	UT	SR-89/114	2001		Bonded					$\overline{\checkmark}$
6	IA	SH-13	2002		Bonded				$\overline{\checkmark}$	
7	IN	I-69	1986		Unbonded		$\overline{\checkmark}$			
8	ОК	I-35	2004		Unbonded		$\overline{\checkmark}$			
9	IA	V-63	2002			Bonded				$\overline{\checkmark}$
10	IL	I-88	1996			Bonded	$\overline{\checkmark}$			
11	MI	US-131	1998			Unbonded		$\overline{\checkmark}$		
12	NC	I-85	1998			Unbonded	$\overline{\checkmark}$			








Case History #1 US-69 Oklahoma

Tech Center

Bonded on Asphalt


- 4" and 6" thickness
- 13 years old
- 10,100,000 ESALs



Case History #1 US-69 Oklahoma



- Typical Section
 - 4" and 6" concrete pavement
 - Slab sizes (w x l): 4' x 6', 6' x 6' and 7' x 6'
 - Existing asphalt pavement milled (approx. 11" remaining)
 - Existing granular base



Case History #1 US-69 Oklahoma

Tech Center


- Constructed adjacent to traffic
- Fiber reinforced (3 lb/yd³)







• Less than 1% cracked slabs after 9 years



Case History #3 CR-56 LaSalle County Illinois






Tech Center

CR-56 LaSalle County Illinois


- Unbonded on Asphalt
- 5" to 7" thick
- 40 years old
- 8,400,000 ESALs





Case History #3 CR-56 LaSalle County Illinois

- Typical Section
 - Variable thickness (5" to 7") concrete pavement
 - Slab sizes (w x l): 12' x 15'
 - Existing asphalt pavement
 - Existing base/subgrade





Case History #3 CR-56 LaSalle County Illinois

- Local traffic maintained during construction
- Integral widening from 18' to 24'



Case History #5 US-89 Utah










Unbonded on Composite


- 4" thick
- Reconstructed after 10 years
- 6,000,000 ESALs



Case History #5 US-89 Utah



- Typical Section
 - 4" concrete pavement
 - Slab sizes (w x l): 4' x 4'
 - Existing concrete pavement with asphalt overlays (milled)
 - Existing base/subgrade







- Local traffic maintained during construction
- Constructed on consecutive weekends
- Fiber reinforced (3 lb/yd³)







- Reconstructed during capacity widening project in 2012
- Early cracking and panel replacement around utility structures



Case History #6 SH-13 Iowa






Case History #6 SH-13 Iowa



Bonded on Composite


- 4" thickness
- 12 years old
- 1,000,000 ESALs







- Typical Section
 - 4" concrete pavement
 - Multiple variations of slab size from 3' to 6' x 6'
 - Existing composite pavement (1931, 7" to 10")
 with asphalt pavement (1964 & 1984, 5")
 - Milled ¼" nominal







• Fiber reinforced (3 lb/yd³)







Minimal repairs after 12 years

Some longitudinal cracking attributed to

tooled joints



Case History #11 US-131 Michigan








US-131 Michigan

Unbonded on Concrete

- ±7" thickness
- 16 years old
- 8,000,000 ESALs





US-131 Michigan (pre-overlay)






US-131 Michigan (9 years later)







- Typical Section
 - ±7" concrete pavement
 - Slab sizes (w x l): 12' x 13'
 - 1" asphalt interlayer
 - Existing concrete pavement (9")
 - 4" granular base on 14" sand subbase







- Constructed adjacent to traffic
- 40% GGBFS
- Crown correction made with variable thickness concrete







- Estimates based on 2012 imagery
 - 18 patches (0.3%)
 - 24 cracked slabs (0.4%) that have been sealed

0.8 mile section experienced early joint

deterioration





QUESTIONS?





THANK YOU!