by

EDWARD J. BRECKWOLDT PAVEMENT RESEARCH ENGINEER

Research Report No.38

Final Report

Research Project No. 68-1M(B) Louisiana HPR 1 (6)

Conducted by
LOUISIANA DEPARTMENT OF HIGHWAYS
Research and Development Section
In Cooperation with
U. S. Department of Transportation
Federal Highway Administration
BUREAU OF PUBLIC ROADS

"The opinions, findings, and conclusions expressed in this publication are those of the author and not necessarily those of the Bureau of Public Roads."

TABLE OF CONTENTS

LIST OF FIGURES	V
LIST OF PHOTOGRAPHS	vii
LIST OF TABLES	ix
SYNOPSIS	xiii
INTRODUCTION	1
METHODOLOGY	2
DISCUSSION OF RESULTS	4
CONCLUSIONS AND RECOMMENDATIONS	6
REFERENCES	7
APPENDIX	11

LIST OF FIGURES

Figure No.	Title	Page No.
1	Field Water Penetration Tests for All Sections, Warm Weather	_ 11
2	Laboratory Water Penetration Tests-Cationic Cores, Warm Weather	_ 12
3	Laboratory Water Penetration Tests-Reclamite Cores, Warm Weather	_ 13
4	Laboratory Water Penetration Tests-Untreated Cores, Warm Weather	_ 14
5	Percent Cationic Cores Penetrated by Foreign Material, Warm Weather	_ 15
6	Percent Reclamite Cores Penetrated by Foreign Material, Warm Weather	
7	Percent Untreated Cores Penetrated by Foreign Material, Warm Weather	17
8	Field Water Penetration Tests One Year After Sealing on Two Eight Year Old Pavements - Cold Weather	_ 18
9	Percent Cores Penetrated by Foreign Material - On Two Eight Year Old Pavements - Warm Weather	_ 19

LIST OF PHOTOGRAPHS

Photograph N	Title	Page No.
1	RS-3K Treated Crack on New Orleans Service Road during September 1968	20
2	RS-3K Treated Crack on New Orleans Service Road during February 1969	20
3	RS-3K Treated Crack on La. 22 during September 1968 -	21
4	RS-3K Treated Crack on La. 22 during February 1969	21
5	Reclamite Treated Crack on New Orleans Service Road during September 1968	22
6	Reclamite Treated Crack on La. 21 during September 1968	22
7	Water Penetration Test on Reclamite Treated Section on La.34 during September 1968	23
8	Untreated Crack on La. 21 during September 1968	23
9	Untreated Crack on La. 21 during February 1969	24
1 0	New Orleans Service Road - Untreated Crack during September 1968	24
11	Axial Cell with Tubular Rubber Membrane	25

LIST OF TABLES

Table No.	Title	Page No.
1	Project Data, Application and Location Information	26
2	Cationic Section Test Data	29
3	Reclamite Section Test Data	32
4	Untreated Section Test Data	37

ACKNOWLEDGEMENTS

The writer wishes to express appreciation to all Maintenance personnel in the nine (9) Districts throughout the State, in particular to the Chief Maintenance and Operations Engineer and the District and District Maintenance Engineers for their assistance in performing and completing this study.

SYNOPSIS

This study is primarily an evaluation of the effectiveness of "Reclamite" when used as a sealant material for reflection cracks. A secondary objective was to determine the performance of our presently used material - cationic emulsified asphalt (RS-3K) and compare the results to those obtained with "Reclamite". This study was limited to and concerned only with reflection cracks that develop in hot mixed asphaltic concrete surfacings which had been placed directly on either Portland Cement stabilized bases or Portland Cement Concrete Pavements.

"Reclamite" is a proprietary product of the Golden Bear Oil Company of California and is a petroleum resin oil base uniformly emulsified with water. This product was specifically designed to penetrate asphaltic surfaces, soften and rejuvenate the asphalt thereby giving longer life. It was suggested that this material, due to its special characteristics, might perform as a very effective crack sealant by softening the asphalt, thereby permitting a kneeding together of the crack interfaces. The Louisiana Department of Highways maintenance forces had been sealing with RS-3K during the winter months when personnel were available and cracks were open. The exact effectiveness of using RS-3K was not known. In addition, in instances where cracks were numerous, sealing often resulted in an unsightly appearance as well as a slick surface.

Reflection cracks are defined as "cracks appearing in a resurface or overlay caused by movement at joints or cracks in underlying base or surface."(*1) As stated their cause is considered to be underlying conditions such as: pavement joints, pavement cracks, shrinkage cracks, etc. These type cracks are of great concern, for if reflection cracks are not kept sealed against the ingress of water and debris, it is felt that serious deterioration of the roadway surfacing may follow, causing possible inferior performance and a reduction in the life of the surfacing.

Louisiana is divided into nine (9) Highway Districts and each District Engineer was contacted and requested to select two (2) projects for this study. The selection was to be made from recent asphaltic concrete surfacing placed directly on either Portland Cement stabilized bases or Portland Cement Concrete Pavements. The projects selected were to be new enough that they had not been sealed and old enough that basic reflection cracking had been established. Seventeen projects, each approximately 6 miles in length were finally selected. Fifteen were approximately one (1) year old and two were approximately eight (8) years old. Each project was then divided into three sections with the first section being sealed with Reclamite, the second section sealed with RS-3K and the third section being left untreated for control purposes. All sealing was done during the winter months between December 1967 and March 1968.

^{* -} Number in parenthesis refer to list of references at end of report.

During the warm weather of September 1968, while the cracks tended to remain closed, the projects were observed and typical cracks selected for core locations and field water penetration tests. Water penetration tests were then run on these representative cracks, both in and out of the wheel paths prior to coring. Cores were then obtained, laboratory tested for water penetration and observed for depth of penetration of foreign matter.

In February 1969, during the cold weather, field water penetration tests were conducted on four (4) typical projects to determine the effects of cold weather.

The results indicate that neither sealant is satisfactory for use and that further studies should be made to evaluate other materials.

Results also indicated that the two eight (8) year old pavements were 78% sealed with foreign matter even prior to placing the sealant materials. This leads to the recommendation that the Department continue to observe the untreated sections used in this study to determine the effects of not sealing and if sealing is desirable or even necessary for reflection cracks occurring on rigid or stabilized bases.

INTRODUCTION

The Louisiana Department of Highways maintenance forces seal reflection cracks in asphaltic concrete surfaces with cationic emulsified asphalt (RS-3K). The exact effectiveness of using this material was not known. In instances where cracks were numerous, use of this material often resulted in a slick and unsightly surface.

Information pertaining to this problem, such as to materials available, sealing practices and performance results, was very limited. It was decided that this study should be undertaken in an effort to learn not only more about our own material and its performance, but to evaluate the effectiveness of "Reclamite" as compared to our presently used RS-3K.

The seventeen (17) projects selected from thoughout the State for this study were primarily recent asphaltic concrete surfacings placed directly on either Portland Cement stabilized bases or Portland Cement Concrete Pavements. These projects were new enough that they had not been previously sealed and old enough that basic reflection cracking had been established. One District had no such projects available and two 8 year old projects which had not been previously sealed were subsequently selected.

All sealing was done during the winter months between December 1967 and March, 1968. Coring and water penetration tests were conducted in September 1968. Four typical projects were tested for field water pentration tests in January, 1969.

METHODOLOGY

Projects were selected on a statewide basis. Louisiana is divided into nine (9) Highway Districts and each District Engineer was contacted and requested to select two (2) projects for this study.

The selection was to be made from recent asphaltic concrete surfacing placed directly on either Portland Cement stabilized bases or Portland Cement Concrete Pavements. The projects selected were to be new enough that they had not been sealed and old enough that basic reflection cracking had been established.

Seventeen projects (each approximately 6 miles in length) were finally selected. Fifteen were approximately one (1) year old and two (2) were approximately eight (8) years old. Each project was then divided into approximately three equal length sections. The first section was sealed with Reclamite, the second section sealed with cationic emulsified asphalt (RS-3K) and the third section was left untreated for control purposes.

All sealing was done during the winter months between December 1967 and March 1968.

For the actual field application Reclamite was used undiluted, agitated in the drums, drawn off into pouring pots and applied directly to the crack. The applied width averaged three inches. Fine sand was then cast upon the Reclamite to prevent traffic from spreading or smearing it and creating a slick surface.

The RS-3K was also applied directly to the crack through the use of the pouring pots in a similar manner.

During the warm weather of September 1968, while the cracks tended to remain closed, the projects were observed and typical cracks were selected for core locations and field water penetration tests. Field water penetration tests were then run on these representative cracks, both in and out of the wheel paths prior to coring.

Approximately 6 cores were taken on each of the three sections for each project as follows. In each section three representative cracks were selected for coring. On each of these three representative cracks two cores were taken, with one core being obtained from the wheelpath and one from outside the wheelpath. For the seventeen (17) projects this made a total of three hundred and six (306) cores. These cores were also laboratory tested for water penetration and were checked for depth of foreign matter penetration. Forty three (43) field water

penetration tests were run during warm weather in September 1968 and one hundred and eight (108) field water penetration tests were run in cold weather the following February 1969.

The test procedure for the field water penetration test consisted of using a one gallon can (6 3/8" diameter), open on both ends (photograph No. 7). The can was sealed to the pavement over the crack by the use of heavy grease placed around the lower edge. The can was then filled with water to a depth of two (2) inches and the water level was remeasured at the end of five minutes. If 1 7/8 to 2 inches of water remained the crack was considered sealed. The length of time required was noted for instances where the can was emptied before the end of the five minute period.

The test procedure for running the laboratory water penetration test employed the use of a lightweight stainless steel cylinder having an inside diameter of 6 3/4 inches and fitted with a standard air valve (photograph No. 11). Inside of each of these cylinders is a tubular rubber membrane, 6 inches in diameter. The core was placed in this cylinder, the lining inflated to approximately 4 psi and an application of heavy grease was used to seal around the top edges of the core and cylinder interface. Two inches of water was then placed in the cylinder above the core. After thirty minutes elapsed time the final depth of water was recorded. If 1 7/8 to 2 inches of water remained the crack was considered sealed. Again if the cylinder was emptied of water before thirty minutes time had elapsed the actual time required for emptying was recorded.

The core was then removed from the cylinder, opened along the crack to inspect for depth of penetration of foreign matter and the depth recorded.

Photographs were taken as deemed necessary throughout the study and are included.

DISCUSSION OF RESULTS

Field Water Penetration Tests - Warm Weather

When the sections were first observed during warm weather it appeared that both Reclamite and Cationic Emulsified Asphalt (RS-3K) were performing as desired. The initial warm weather field water penetration tests showed (Figure 1) that the RS-3K had 91.7% effectively sealed the reflection cracks against water (Photograph Nos. 1 & 3). Reclamite had sealed only 81.2%, however the wheel paths for both Reclamite and RS-3K were 100% sealed. This indicates that Reclamite is 100% effective only in the wheel path where a kneeding action is present. The untreated sections were only 46.7% sealed even under ideal conditions of warm weather (Photograph No. 8).

Laboratory Water Penetration Tests - Cores obtained during warm weather

The Laboratory water penetration tests run on cores obtained during warm weather verified the above results, in that cracks sealed with RS-3K resisted water penetration better than did those sealed with "Reclamite" or the unsealed cracks. (Figures 2, 3 and 4).

Laboratory Foreign Matter Penetration Tests - Cores obtained in warm weather

Again these results were in agreement with above data, in that the RS-3K was the most effective in preventing infiltration of foreign material. Cracks sealed with Reclamite had less penetration of foreign material than did the unsealed cracks. (Figures 5, 6 and 7). It was noted that for 77.7% of the cores obtained from the untreated sections the foreign material had penetrated to a depth of more than 2 inches. It was also especially noted that this material was not tightly packed.

Field Water Penetration Tests - Cold Weather

A. Two eight year old projects excluded.

When the projects were visited during cold weather it was observed that all cracks on all projects had opened to the extent that it was impractical to even continue running the field water penetration tests. After running 54 tests the results showed that none of the cracks were effectively sealed against water penetration during cold weather. (Photograph Nos. 4 and 9).

B. Two eight year old projects only.

It was interesting to note (Figure 8) that the reflection cracks on the two eight (8)

year old projects were tightly packed and almost sealed (78% not penetrated by water) with foreign matter even prior to placing any sealant material. (Photograph No. 10).

The application of the Reclamite material to these cracks brought the effectiveness of the seal to 100%, whereas the RS-3K only increased this effectiveness to 90%. (Photograph No. 2). Review of the data (Figure 9) showed that the cracks in the Reclamite section had possibly been better sealed initially by foreign matter than were the cracks in the RS-3K section.

CONCLUSIONS AND RECOMMENDATIONS

Reclamite and cationic emulsified asphalt (RS-3K) are not satisfactory for use in sealing reflection cracks on rigid or stabilized bases. Except for the two eight (8) year old projects which were sealed with foreign matter all cracks were open during the winter season. FURTHER STUDIES SHOULD BE MADE TO EVALUATE OTHER MATERIALS.

The two eight (8) year old pavements were 78% sealed with foreign matter even prior to placing the sealant materials.

IT IS RECOMMENDED THAT THE DEPARTMENT CONTINUE TO OBSERVE THE UNTREATED SECTIONS USED IN THIS STUDY TO DETERMINE THE EFFECTS OF NOT SEALING AND IF SEALING IS DESIRABLE OR EVEN NECESSARY FOR REFLECTION CRACKS OCCURRING ON RIGID OR STABILIZED BASES.

REFERENCES

l. "AASHO Highway Definitions" Prepared by Special Committee	on Nomenclature
Adopted by the American Association of State Highway Officials -	June 1968,
Page 12.	







Figure 1: All Projects - Warm Weather September 1968











Figure 5: September 1968







Figure 7: September 1968







Figure 9: Two Eight Year Old Pavements September 1968



Photograph No. 1: RS-3K Treated Crack on New Orleans Service Road During September 1968




Photograph No. 2: RS-3K Treated Crack on New Orleans Service Road During February 1969



Photograph No. 3: RS-3K Treated Crack on La. 22 During September 1968



Phylograph No. 1: RS-A Treated Crack on La. 22 During February 1969



Photograph No. 5: Reclamite Treated Crack on New Orleans Service Road During September 1968




Photograph No. 6: Reclamite Treated Crack on La. 21 During September 1968




Photograph No. 7: Water Penetration Test on Reclamite Treated Section on La. 34 During September 1968




Photograph No. 8: Untreated Crack on La. 21 During September 1968



Photograph No. 9: Untreated Crack on La. 21 During February 1969



Photograph No. 10: New Orleans Service Road - Untreated Crack During September 1968



Photograph No. 11: Axial Cell With Tubular Rubber Membrane

PROJECT DATA
APPLICATION AND LOCATION INFORMATION

TABLE 1

		711 1 1	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
Date of Application - Reclamite	Temp. at Time of Application	Dist.	Hwy. No.	Location of Reclamite Section	Location of Cationic and Control Sections
12-20-67	45 °	61	67	North of Jct. of 67 & 74 in northbound lane	Southbound lane and north of Reclamite section
1-8-68	32°	61	1 90	West of the Amite River Bridge in the westbound lane	West of the Reclamite section
1-16-68	40° to 60°	58	124	Begin 10.75 miles south of the Jct. of 84 & 124 in Jonesville, Louisiana	South of the Reclamite section
1-18-68	50° to 70°	58	566	Begin at the Jct. of 566 & 751 north of Clayton proceed East	East of the Reclamite section
1-25-68	45° to 70°	8	1	Begin at the Jct. of 1 & 498	North of the Reclamite section

and proceed North

Begin at Jct. of 10 and proceed Southeast

Begin 6.86 miles East of

the Cameron Parish Line

and proceed West

Southeast of the Reclamite section

West of the Reclamite section

1-18-68	50° to 70°
1-25-68	45° to 70°
1-25-68	

8

3

3

71

82

PROJECT DATA APPLICATION AND LOCATION INFORMATION

	Date of Application - Reclamite	Temp. at Time of Application	Dist.	Hwy. No.	Location of Reclamite Section	Location of Cationic and Control Sections
	1-30-68	70°	4	171	Begin at the end of concrete on 171, South of the Jct. of 171 and 84, proceed South	South of the Reclamite section
	2-7-68	45° to 60°	5	34	Begin at the Jct. of 34 & 557 and proceed West	West of the Reclamite section
	2-8-68	35° to 40°	5	34	Begin at the Jct. of 34 & 4 and proceed North	North of the Reclamite section
27	2-13-68		62	21	Begin at the first bridge North of the East Jct. of 436 & 21 and proceed North	North of the Reclamite section
	2-14-68		62	22	Begin 2 miles East of the Tangipahoa Parish Line	East of the Reclamite section
	2-28-68	50°	3	90	Begin at first Overpass East of Crowley on U.S. 90	East of the Reclamite section
	3-5-68	60° to 70°	2		Begin at the Southwest corner of the Westbank expressway and Barataria Boulevard on the South Service Road and proceed West	West of the Reclamite section
	3-7-68	40°	2	18	Begin where La. 18 turns East off Barataria Boulevard and proceed East	East of the Reclamite section

TABLE 1 (CONTINUED)

PROJECT DATA APPLICATION AND LOCATION INFORMATION

Date of Application - Reclainite	Temp. at Time of Application	Dist.	Hwy. No.	Location of Reclamite Section	Location of Cationic and Control Sections
3-13-68	45 °	7	167	Begin at the Jct. of 10 & 167, one mile West of Ville Platte and proceed North in northbound lane	Southbound Lane
3-14-68	50°	7	95	Begin in Mamou at the Jct. of 104 & 95 and proceed East in the eastbound lane	Westlmand Lane

CATIONIC SECTION TEST DATA

		Approx.		Laboratory Water Penetration	Penetration By	,	Field Wa Penetrat Height R	ion Tes	
Highway	Core	Âge,	Thickness	Test-Height, Inches	Foreign Material		nmer		nter
Number	Number	Years	Inches	Remaining Cores	Depth, Inches	С	W.P.	С	<u>W.P.</u>
18	327	8	2	-	0.0			0.0	
18	328	8	1 5/8	_	0.0			0.0	
18	329	. 8	2 1/2	-	0.0			2	
90	348	1	2 1/4	2.00	0.0	2			
90	349	1		2.00	_				
90	350	1	4 3/4	0.0	2.5				
90	351	1	5 1/2	0.0	3.25				
90	352	1	1 3/4	1.0	0.0				
90	353	1	1 3/4	1.5	0.0				
90	354	1	-	2.0		2			
21	373	1	3 5/8	0.0	3.63			0.0	0.0
21	374	1	3 3/4	2.0	3.75			0.0	0.0
21	375	1	3 3/4	1.75	1.5			0.0	0.0
21	376	1	3 3/4	1.75	3.75			0.0	
21	377	1	3 1/2	0.0	3.50			0.0	
21	378	1	3 3/4	0.25	1.5			0.0	
22	391	1	-	1.25	-	1 7/8	3	0.0	0.0
22	392	1	3 1/2	0.75	3.5			0.0	0.0
22	393	1	3 7/8	2.0	0.0			0.0	0.0
22	394	1	1 1/2	1.25	0.0			0.0	
22	395	1	1 3/4	2.00	0.0			0.0	
22	396	1	1 3/4	2.00	0.0			0.0	

RECLAMITE SECTION TEST DATA

Highway Number	Core Number	Approx. Age, Years	Thickness, Inches	Laboratory Water Penetration Test-Height, Inches Remaining Cores	Penetration By Foreign Material Depth, Inches	Height Summer	ation Tests Remaining,Inches
Number	Number	1 Cars	menes	recinating Coles	Depth, Inches	<u></u>	
67	1						
67	2	1		1.16			
67	3	· 1	4	1.94	4.0		
67	4	1	4 1/4	1.50	0.0		
67	5	1	4	0.50	4.0		
67	6	1	3 3/4	1.95	3 . 75		
67	7	1	4	0.0	4.0		N.
67	8	1	3 3/4	0.0	3.75		
67	9	1	3 1/2	0.00	3.5		
67	10	1	4	1.38	1.00		
67	11	1		0.0	-		
67	12	1	3	None	0.0		
67	13	1	4	0.0	4.0		
67	14	1		0.0	-		•
190	26	1	4 1/2	0.0	1		
190	27	1	1 3/4	0.0	1.75		
190	2 8	1	3 3/4	0.64	3 . 75		
190	29	1	3 1/2	1.10	0.25		
190	30	1	5 1/4	1.30	5.25		
1 90	31	1		0.0	_		
190	32	1	3 1/2	0.78	3 . 5		
190	33	1	3 1/4	0.0	3.25		
190	34	1	3 1/4	0.0	3.25		
190	35	1	3 3/8	0.10	0.0		
190	36	1	3/58	0.0	3.63		
34	60	1	3 7/8	1.97	0.0		
34	61	1	4 1/8	2.0	0.0	2	

	Highway	Core	Approx. Age,	Thickness,	Laboratory Water Penetration Test-Height, Inches	Penetration By Foreign Material	P H	Tield Wate Tenetration Teight Res Teight Res	n Tes maini	sts ng,Inches inter
	Number	Number	Years	Inches	Remaining Cores	Depth, Inches	C	W.P.	C	W.P.
	2.4	/ 3	7	2.1/4	2 0					
	34	62	1	3 1/4	2.0	0.0				
	34	63	1	3 3/8	2.0	0.0		2		
	34	64	. 1	3 1/4	0.16	0.0	_			
	34	65	1	3 1/4	1.50	0.0	2			
	-	-	-	_						
	34	70	1	3	2.0	0.5		2		
	34	71	1	3 3/4	1.66	3.75				
<u>ر</u>	34	72	1	3 3/4	0.25	0.0				
•	34	85	1	3 1/4	2.0	0.0				
	34	86	1	3	0.75	0.0				
	171	87	1	3	0.0	0.0				
	171	88	1	4	0.0	4.0				
	171	89	1	3 3/8	0.25	3.38				
	171	90	1	3 1/8	1.25	3.12				
	171	91	1	4 3/8	0.0	4.38				
	171	92	1	4.3/8	0.0	4.38				
	1	99	1	4 1/2		0.0				
	1	100	1	3 1/4	2.0	0.0				
	1	101	1	3 1/2	1.5	0.0				
	1	102	1	2 3/4	2.0	0.0				
	1	103	1	3 1/2	1.5	0.0				
	1	104	1	2 1/2	2.0	2.5				
	566	111	1	1 3/4	0.75	0.0				
	566	112	1	1 3/4	1.5	0.0	1 5/	8		
	566	113	1	2	2.0	0.0	- 0,	-		
	566	114	1	1 3/4	1.25	1.75	1 1/	12		
	566	115	1	1 3/4	2.0	0.0	1 1/	4		
	566	116	1	1 5/8	0.0	1.62				
	500	110		1 3/0	0.0					

ن

TABLE 3 (CONTINUED)

Field Water

RECLAMITE SECTION TEST DATA

			Penetration Tests						
		Approx.		Laboratory Water Penetration	Penetration By				ing,Inches
Highway	Core	Age,	Thickness,	Test-Height, Inches	Foreign Material		immer		ing, inches inter
Number	Number	Years	Inches	Remaining Cores	Depth, Inches	C	W.P.	C"	W.P.
TVGIII DOI	TVallibe 1	10415	1101100	icentaning cores	Deptil, Inches		VV . I .		
124	129	1	1 3/4	0.0	1.75				
124	130	1		2.0	_	2			
124	131	· 1	1 1/2	1.5	0.25				
124	132	1	1 1/2	1.16	1.5				
124	133	1	1 3/4	0.0	1.75				
124	134	1	1 3/4	1.75	1.75				
1	147	1		0.0	_				
1	148	1	1 3/4	2.0	1.75	2			
1	149	1	1 3/4	2.0	1,75				
1	150	1	5 1/2	2.0	5 . 5				
1	151	1	5	2.0	0.0				
1	152	1	5 1/4	2.0	5.25				
1	165	1	1 3/4	2.0	1.75				
1	166	1	1 1/2	0.0	1.5	2			
1	167	1	1 3/4	1.25	0.25				
1	168	1	$1 \ 1/4$	0.62	1.25				
1	169	1	1	0.0	1.0				
1	170	1	1	0.0	1.0				
167	183	1	2 1/4	2.0	2.0				
167	184	1	3 3/4	2.0	2,0	2			
167	185	1	3 1/2	0.0	0.25				
167	186	1	3 1/4	1.5	0.25				
167	187	1		1.5	-				
167	188	1	3 1/4	2.0	3.25				
Frontage									
Road	300	8	1 7/8	0.0	1.87			2	2
Frontage									-
Road	301	8	1 5/8	0.0	1.63	2		2	2

RECLAMITE SECTION TEST DATA

	Highway	Core	Approx.	Thickness,	Laboratory Water Penetration Test-Height,Inches	Penetration By Foreign Material	Summer	tion Tes Lemainii Wir	ng,Inches nter
	Number	Number	Years	Inches	Remaining Cores	Depth, Inches	<u>C W.P</u>	. <u>C</u>	<u>W.P.</u>
	Frontage								
	Road	302	8		0.0	_		2	2
	Frontage		Ü		•				2
	Road	303	. 8	1 3/4	0.0	1.75		2	
	Frontage			·				_	
	Road	304	8	1 1/2	1.75	0.0		2	
	Frontage								
ง n	Road	305	8	2 1/8	1.25	2.12		2	
п	18	318	8	1 7/8	0.0			2	2
	18	319	8		0.0	-	2	2	2
	18	320	8		0.0	-		2	2
	18	321	8	2	0.0	2.0		2	
	18	322	8	2	0.0	2.0		2	
	18	323	8	2	0.0	0.0		2	
	90	342	1	3	1.85	1	2		
	90	343	1	2	2.0	0.0			
	90	344	1	1 1/4	1.66	0.0			
	90	345	1	1 1/2	0.0	0.0			
	90	346	1		1.25	-			
	90	347	1	2	2.0	0.0			
	82	355	1	2 1/2	2.0	0.0	1 15/16		
	82	356	1	2 1/2	2.0	0.0			
	82	357	1	2 1/2	0.50	0.0			
	82	358	1	2 3/8	1.75	0.0			
	82	359	1	2 1/4	1.25	0.0			
	82	360	1	2 1/4	1.75	0.0			
	21	367	1	3 1/2	0.00	0.0	1 1/2	0.0	0.0
	21	368	. 1	3 3/4	0.0	0.0		0.0	0.0

RECLAMITE SECTION TEST DATA

TABLE 3 (CONTINUED)

Highway Number	Name t			Laboratory Water Penetration Test-Height, Inches Remaining Cores	Penetration By Foreign Material Depth, Inches	Fen e Heigi Jame	Water tration Te at Remaini er T.P. C	
sets to	ges je			ing yan	00		0.6	
man' '	S. S.			, 25	0.0		0.0	6.0
	mark . W			· , Ø	S ,		0.0	
	11.1			. 3.5	0.0		0.0	
\tilde{Z} \dot{z}	* ", "			75	6.0		0.0	
and or	And the second		Ą	Control	0.0	t j. si	0.0	0.0
2.2	9.8 c		41/4	, 26	*		0.0	C 0
31 31 32 32 32 33 33 33 33 34 35	307	2	3. 3. / 1.	.0	0.25		0.0	0.0
i jang lang Kanangan	385	*	1 3/4		6.5		0.0	

0.0

0.0

339 1 4 ..65

390

TABLE 4

UNTREATED SECTION TEST DATA

				Laboratory		Field Wat Penetrati	
		Approx.		Water Penetration	Penetration By	Height Re	emaining, Inche
Highway	Core	Age,	Thickness,	Test-Height, Inches	Foreign Material	Summer	Winter
Number	Number	Years	Inches	Remaining Cores	Depth, Inches	C W.P.	<u>C W.P.</u>
67	15	1	4	0.0	4.0		
67	16	1	3 1/2	0.0	3.5		
67	17	. 1	4 1/4	0.0	4.25		
67	18	1	3 1/2	0.0	3.5		
67	19	1	3 3/4	0.0	3.75		
67	20	1	3 3/4	0.0	3.75		
67	21	1	-	0.0	-		
67	22	1	3 7/8	1.08	3.87		
³⁷ 67	23	1	4	0.0	4.0		
67	24	l	3 3/4	0.0	3.75		
67	25	1	4	0.0	4.0		
190	37	1	3 1/4	0.0	3.25		
190	38	1	3 1/4	0.0	3.25		
190	39	1	3 1/4	0.0	3.25		
190	40	1	3 1/2	0.0	3.50		
190	41	1	3	0.0	3.0		
190	42	1	3 1/2	0.0	3.5		
190	43	l	4	0.0	4.0		
190	44	1	3 3/4	0.0	3.75		
190	45	1	-	0.0	-		
190	46	1	3 3/4	0.0	3.75		
190	47	1	4	0.42	4.0		
190	48	1	-	0.0	-		
34	49	l	3 3/4	1.45	3.75		
34	50	1	3 1/2	0.0	3.5	1/4	
34	51	1	3 1/2	0.50	1.0		
34	52	1	3 1/4	1.16	1.0	3/4	
34	53	1	3	0.16	3.0		

TABLE 4 (CONTINUED)

Field Water

UNTREATED SECTION TEST DATA

Highway	Core	Approx.	Thickness,	Laboratory Water Penetration Test-Height, Inches	Penetration By Foreign Material	Penetration Tests Height Remaining, Inch Summer Winter				
Number	Number	Years	Inches	Remaining Cores	Depth, Inches	C W.P. C	<u>W.P.</u>			
34	54	1	3	0.75	3.0	1				
34	55	1	4 1/4	0.0	4.25					
34	56	1	3 1/4	0.85	0.0					
34	57	. 1	3 3/8	0.0	0.50					
34	58	1	3 3/4	0.85	3.75					
34	59	1	4	1.10	0.0	1 1/2				
34	73	1	3	0.0	3.0					
3 1	74	1	3	0.0	3.0					
34	75	1	3 1/4	0.0	3.25					
34	76	1	3	0.0	3.0					
34	77	1	3 1/4	0.0	1.0					
34	7 8	1	3 1/4	0.25	1.5					
171	93	1	3 1/2	0.25	3.5					
171	94	1	3 3/8	0.0	3.37					
171	95	1	3 1/4	0.0	3.25					
171	96	1	3	2.0	0.0					
171	97	1	3 1/2	0.0	3.5					
171	98	1	3 1/4	0.0	3.25					
1	105	1	~~	0.0						
1	106	1	-	0.0	-					
1	107	1	4 3/4	0.0	4.75					
1	108	1	2 1/2	0.0	2.5					
1	109	1	3 1/2	2.0	0.0					
1	110	1	3	2.0	3.0					
-//	172	1	1 1/2	0 66	1 5					

TABLE 4 (CONTINUED)

UNTREATED SECTION TEST DATA

	Highway	Core	Approx.	Thickness,	Laboratory Water-Penetration Test-Height, Inches	Penetration By Foreign Material	Pen Heig Summ	ght Rer	n Tests maining, Inc Winter CW.P	
	Number	Number	Years	Inches	Remaining Core	Depth, Inches		v . P	<u> </u>	<u>. </u>
	566	124	1	-	0.0	-				
	566	125	1	1 1/2	0.0	1.5				
	566	126	· 1	1 3/4	0.0	1.75	1/2			
	566	127	1	1 1/2	1.5	1.5				
	566	128	1	$1 \ 1/4$	0.0	1.25				
	124	141	1	1 1/2	0.0	1.5				
(.)	124	142	1	1 1/2	1.0	1.5	2			
39	124	143	1	1 1/2	0.0	1.5				
	124	144	1	-	0.0	-				
	124	145	1	1 5/8	0.0	1.63				
	124	146	1	2	0.0	2.0				
	1	159	l	4 3/4	0.0	4.75				
	1	160	1	-	1.25	-	2			
	1	161	1	4	1.75	0.0				
	1	162	1	4 1/2	0.0	4.5				
	1	163	1	4 1/4	0.0	4.25				
	1	164	1	4 3/4	0.0	4.75				
	1	171	1	1 3/4	0.0	1.75				
	1	172	1	1 5/8	2.0	1.0	2			
	1	173	1	1 3/4	2.0	1.75				
	1	174	1	-	2.0	-				
	1	175	1	1 1/4	0.0	1.25				
	1	176	1	1 1/4	0.0	1.25				
	167	189	1	3 3/4	2.0	3.75				
	167	190	1	3 1/2	0.0	3.50	2			

TABLE 4 (CONTINUED)

UNTREATED SECTION TEST DATA

Number Number Number Vears Inches Remaining Core Depth, Inches C W.P. C W.P.	1	Highway	Core	Approx. Age,	Thickness,	Laboratory Water Penetration Test Height, Inches	Penetration By Foreign Material	Pen		n Tes	g, Inches
167]	Number	Number	Years	Inches	Remaining Core	Depth, Inches	C W	.P.	С	W.P.
167	-							est year our faculty extress — Therefore			
167		167	191	1	3 3/4	1.5	0.0				
167		167	1 92	1							
167		167	193	. 1	4 1/4						
Frontage Road 312 8 21/4 1.25 2.25 2 2 Frontage Road 313 8 2 1 7/8 2.00 1.5 2 2 2 Frontage Road 314 8 2 2 2.00 2.0 2.0 2 2 Frontage Road 315 8 2 2.00 2.0 2.0 2 2 Frontage Road 316 8 2 2.00 2.0 2 2 Frontage Road 316 8 1 3/4 0.0 1.75 2 2 Frontage Road 316 8 2 1/2 0.0 2.5 2 Frontage Road 317 8 2 1/2 0.0 2.5 2 18 330 8 2 - 0.0 0.0 2.5 2 18 331 8 0.0 0.0 0.0 1.87 2 2 18 333 8 0.0 0.0 0.0 0.0 1.87 2 2 18 333 8 0.0 0.0 0.0 0.0 1.88 333 8 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0		167	194	1	-						
Frontage Road 313 8 2 2 2.00 1.5 2 2 2 Frontage Road 315 8 2 2.00 2.0 2.0 2 2 Frontage Road 315 8 2 2.00 2.0 2.0 2 Frontage Road 316 8 1 3/4 0.0 1.75 2 2 Frontage Road 317 8 21/2 0.0 2.5 2 18 330 8 2 0 0.0 2.5 2 18 331 8 0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0		Frontage									
Frontage Road 313 8 17/8 2.00 1.5 2 2 2 Frontage Road 314 8 2 2.00 2.00 2.0 2.0 2 2 Frontage Road 315 8 2 2.00 2.00 2.0 2.0 2 Frontage Road 316 8 13/4 0.0 1.75 2 2 Frontage Road 316 8 21/2 0.0 2.5 2 18 330 8 2 0 0.0 2.5 2 18 331 8 0 0.0 0.0 2.5 2 18 331 8 0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0		Road	312	8	2 1/4	1.25	2.25			2	2
Frontage Road 314 8 2 2.00 2.0 2 2 Frontage Road 315 8 2 2.00 2.0 2 Frontage Road 316 8 1 3/4 0.0 1.75 2 Frontage Road 317 8 2 1/2 0.0 2.5 2 18 330 8 2 - 0.0 0.0 0.0 18 331 8 2 2 2 18 332 8 1 7/8 - 1.87 2 2 18 333 8 2 2 2 18 333 8 2 2 18 333 8 2 18 334 8 2 18 335 8 0.0 18 336 1 1 3/4 90 337 1 3 3/8 1.16 3.37	42	Frontage									
Road 314 8 2 2.00 2.0 2 2 Frontage Road 315 8 2 2.00 2.0 2 2 Frontage Road 316 8 1 3/4 0.0 1.75 2	0.1	Road	313	8	1 7/8	2.00	1.5	2		2	2
Frontage Road 315 8 2 2.00 2.0 Frontage Road 316 8 1 3/4 0.0 1.75 2 Frontage Road 317 8 2 1/2 0.0 2.5 2 18 330 8 2 - 0.0 0.0 0.0 0.0 1.8 331 8 2 2 2 2 18 333 8 2 2 2 2 18 333 8 2 2 2 18 334 8 2 0.0 0.0 1.87 2 2 18 335 8 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0		Frontage									
Road 315 8 2 2.00 2.0 2 Frontage Road 316 8 1 3/4 0.0 1.75 2 Frontage Road 317 8 2 1/2 0.0 2.5 2 18 330 8 2 - 0.0 0.0 0.0 18 331 8 - - - 2 2 2 18 332 8 1 7/8 - 1.87 2 2 2 18 333 8 - - - 2 2 2 18 334 8 - - - 0.0 0.0 18 335 8 - - - 0.0 0.0 90 336 1 - - - 1 3/4 90 337 1 3 3/8 1.16 3.37		Road	314	8	2	2.00	2.0			2	2
Frontage Road 316 8 1 3/4 0.0 1.75 Frontage Road 317 8 2 1/2 0.0 2.5 18 330 8 2 - 0.0 18 331 8 2 2 2 18 332 8 1 7/8 - 1.87 2 2 2 18 333 8 - 2 2 18 334 8 - 2 2 18 335 8 - 2 2 18 335 8 - 2 2 19 336 1 - 2 2 90 336 1 - 2 3/8 1.16 3.37		***									
Road 316 8 1 3/4 0.0 1.75 2 Frontage Road 317 8 2 1/2 0.0 2.5 2 18 330 8 2 - 0.0 0.0 0.0 0.0 18 331 8 - - - 2 2 2 18 332 8 1 7/8 - - 2 2 2 18 333 8 - - - 2 2 18 334 8 - - - 0.0 18 335 8 - - - 0.0 90 336 1 - - - 1 3/4 90 337 1 3 3/8 1.16 3.37			315	8	2	2.00	2.0			2	
Frontage Road 317 8 2 1/2 0.0 2.5 18 330 8 2 - 0.0 18 331 8 2 2 2 18 332 8 1 7/8 - 1.87 2 2 18 333 8 2 2 18 334 8 2 0.0 18 335 8 2 10.0 18 337 1 3 3/8 1.16 3.37											
Road 317 8 2 1/2 0.0 2.5 2 18 330 8 2 - 0.0 0.0 0.0 0.0 18 331 8 - - - 2 2 2 18 332 8 1 7/8 - - 2 2 18 333 8 - - - 2 2 18 334 8 - - - 0.0 18 335 8 - - - 0.0 90 336 1 - - - 1 3/4 90 337 1 3 3/8 1.16 3.37			316	8	1 3/4	0.0	1.75			2	
18 330 8 2 - 0.0		_									
18 331 8 - - - 2 2 2 18 332 8 1 7/8 - 1.87 2 2 18 333 8 - - - 2 2 18 334 8 - - - 0.0 18 335 8 - - - 0.0 90 336 1 - - - 1 3/4 90 337 1 3 3/8 1.16 3.37						0.0				2	
18 332 8 1 7/8 - 1.87 2 2 18 333 8 - - - 2 18 334 8 - - - 0.0 18 335 8 - - - 0.0 90 336 1 - - - 1 3/4 90 337 1 3 3/8 1.16 3.37					2	~	0.0			0.0	0.0
18 333 8 - - 2 18 334 8 - - 0.0 18 335 8 - - - 0.0 90 336 1 - - - 1 3/4 90 337 1 3 3/8 1.16 3.37						~			2	2	2
18 334 8 - - 0.0 18 335 8 - - 0.0 90 336 1 - - - 1 3/4 90 337 1 3 3/8 1.16 3.37					1 7/8	~	1.87				2
18 335 8 0.0 90 336 1 13/4 90 337 1 33/8 1.16 3.37					-	-	-			2	
90 336 1 1 3/4 90 337 1 3 3/8 1.16 3.37					-	-	-				
90 337 1 33/8 1.16 3.37					. -	-	-			0.0	
, , , , , , , , , , , , , , , , , , , ,		•		1		-		1 3/4			
90 338 1 3 1/2 2.0 3.5		•		1							
		90	338	1	3 1/2	2,0	3.5				

TABLE 4 (CONTINUED)

	Highway Number	Core Number	Approx. Age, Years	Thickness, Inches	Laboratory Water Penetration Test-Height, Inches Remaining Core	Penetration By Foreign Material Depth, Inches	F H	Pield Wat Penetration Ieight Re mmer W.P.	on Te main	ests ing, Inch Vinter W.P.
	90	339	1	3 3/4	2.0	0.5				
	90	340	1	3 3/4	0.0	3.75				
	90	341	. 1	3 1/2	1.75	3.5				
	82	361	1	1 3/4	0.0	0.0		1 7/8		
	82	362	1	2 1/2	1.25	0.25				
	82	363	1	2 1/2	1.75	0.50				
	82	364	1	3 1/4	0.25	1.0				
41	82	365	1	2 1/2	1.50	0.25				
	82	366	1	2 1/8	0.0	2.12				
	21	379	1	3 3/8	0.16	3.37	2.0			
	21	380	1	3 3/4	2.0	1.0				
	21	381	1	3 1/2	1.0	3.5				
	21	382	1	3 1/2	0.0	3.0				
	21	383	1	3 3/8	2.0	1.0				
	21	384	1	3 1/4	0.0	3 .2 5				
	22	397	1	2	0.0	2.0	1 1/	4		
	22	398	1	1 1/4	O • O	1.25				
	22	399	1	4	0.0	4.0				
	22	400	1	4 1/2	0.0	4.5				
	22	401	1	1 1/4	0.0	1.25				

0.0

1.25

1 1/4

22

402